HISTORIC AMERICAN BUILDINGS SURVEY

HABS No. NY-5688

INDEX TO PHOTOGRAPHS

New York County Courthouse (Tweed Courthouse) 52 Chambers Street New York City New York County New York

Documentation:

7 exterior photos (1979)

27 interior photos (1979)

Walter Smalling, Jr. Photographer September 1979

NY-5688-1 NORTH, MAIN FACADE

NY-5688-2 NORTH, MAIN FACADE & PORTICO

NY-5688-3 NORTH FACADE, MAIN ENTRANCE PORTICO

NY-5688-4 SOUTHEAST ANGLE

NY-5688-5 EAST FACADE

NY-5688-6 SOUTHEAST CORNER

NY-5688-7 CORNER OF EAST END

NY-5688-8 STAIRWAY, WEST WING, 2nd FLOOR

NY-5688-9 STAIRWAY, WEST WING, 2nd FLOOR

NY-5688-10 INTERIOR, COURTYARD 2nd FLOOR, VIEW TO NORTH

NY-5688-11 COURTYARD, 2nd FLOOR, RAILING DETAIL

NY-5688-12 INTERIOR, COURT, 2nd FLOOR

NY-5688-13 INTERIOR, COURTYARD, SCULPTURE NICHE

NY-5688-14 INTERIOR, 2nd FLOOR, VIEW FROM EAST WING STAIRHALL TO COURT

NY-5688-15 INTERIOR, COURT

NY-5688-16 INTERIOR, 2nd FLOOR, WEST WING

(continued)

NY-5688-17	INTERIOR, SECOND FLOOR, COURT CHAMBER, DOOR DETAIL
NY-5688-18	INTERIOR, 2nd FLOOR, WEST WING, CEILING MEDALLION
NY-5688-19	INTERIOR, 2nd FLOOR, WEST WING
NY-5688-20	DETAIL, STAIRWAY, SOUTHEAST CORNER, INTERIOR
NY-5688-21	INTERIOR, ELEVATOR GRILL, GROUND FLOOR, SOUTH WING
NY-5688-22	INTERIOR, STAIRWAY, SOUTH WING, 2nd FLOOR
NY-5688-23	INTERIOR, SOUTH WING, 3rd FLOOR
NY-5688-24	INTERIOR, SOUTH WING, 3rd FLOOR, CHAMBER
NY-5688-25	INTERIOR, SOUTH WING, 3rd FLOOR, CHAMBER
NY-5688-26	INTERIOR, SOUTH WING, 3rd FLOOR CHAMBER, COLUMN DETAIL
NY-5688-27	INTERIOR, SOUTH WING, CHAMBER, 3rd FLOOR, CEILING DETAIL
NY-5688-28	INTERIOR, SOUTH WING, CHAMBER 3rd FLOOR, FLOOR MOSAIK DETAIL
NY-5688-29	INTERIOR, SOUTH WING, 3rd FLOOR CHAMBER, FIREPLACE DETAIL
NY-5688-30	INTERIOR, 2nd FLOOR, EAST SIDE COURT ROOM, DOOR PEDIMENT & CEILING DETAIL
NY-5688-31	INTERIOR, 2nd FLOOR, COURTROOM, EAST WING
NY-5688-32	INTERIOR, 2nd FLOOR, COURT CHAMBER, NE CORNER
NY-5688-33	INTERIOR, 3rd FLOOR HALLWAY, EAST SIDE
NY-5688-34	INTERIOR, DOOR DETAIL, 3rd FLOOR, EAST WING